CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182611 Address: 901 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Rated Assembly Inspection		Inspector:	Outcome:	Date:
		Mark Harding	Partial	Thursday, March 12, 2020
Partial Co	rrection:			
2	THE FOLLOWING AREAS ARE APPROVED	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT ELEVATOR SHAFT: BETWEEN TRUSS JOISTS: BASEMENT LEVEL: BACKSIDE PRE-ROCK 2 LAYERS 1ST FLOOR: BACKSIDE PRE-ROCK 2 LAYERS 2ND FLOOR: BACKSIDE PRE-ROCK 2 LAYERS		
		3RD FLOOR: BACKSID		
Corrective	e Action Required:			
3	STAIR TOWER 1	EAST STAIRWELL OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT STAIRWELLS INSIDE FACE & BACKSIDE PRE-ROCK BETWEEN JOISTS: #1: BASEMENT LEVEL: 1ST LAYER; 2ND LAYER 1ST FLOOR: 1ST LAYER; 2ND LAYER 2ND FLOOR: 1ST LAYER; 2ND LAYER 3RD FLOOR: 1STLAYER; 4TH FLOOR:		
Corrective	e Action Required:			
4	STAIR TOWER 2	WEST- EAST STAIRWELL #1:		

BASEMENT LEVEL: 1ST LAYER; 2ND LAYER 1ST FLOOR: 1ST LAYER; 2ND LAYER 2ND FLOOR: 1ST LAYER; 2ND LAYER 3RD FLOOR: 1ST LAYER; 4TH FLOOR:

Comments: