

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192706
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|--|------------|----------|---------------------------|
| Underslab Electrical Inspection - Mark Harding Commercial | | Partial | Monday, March 16, 2020 |

Partial Correction:

| | | |
|-----------------------------|--|--|
| 1 | Misc | NO ISSUES FOUND ON UNDER-SLAB ELECTRICAL CONDUIT MATERIAL & WORKMANSHIP. OK TO COVER WHEN READY AT: NW CORNER OF BUILDING TO ~60' S/SE TWENTY-TWO 3" CONDUITS & TWO 2" CONDUITS; FIVE 3" SOUTH TO (7) AT METER BANK 2B; ONE 3" FROM NW CORNER TO W/I 20' OF ELEVATOR C; SEVEN 3" & TWO 2" FROM NW CORNER TO F/12; SEVEN 3" & TWO 2" RE-ROUTED FROM F/12 TO B2A AT A/7.5; SEVEN 3" & TWO 2" FROM 1/A.5 TO E SIDE OF COLUMN 1/F; |
| | | G.C. AND E.C. TO ENSURE LAYOUT IS CORRECT. OK TO COVER WHEN READY. |
| Corrective Action Required: | | |
| 2 | THE FOLLOWING AREAS ARE APPROVED | SECONDARY FROM METER BANKS TO TURN UP IN PARKING GARAGE. SOUTH METER BANK--: B LINE1-4; ELEVATOR LINE- B-G,G 1.5-5.- A ELEVATOR. |

Comments: