

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182611
Address: 901 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Khanh Nguyen	Partial	Wednesday, March 25, 2020

Partial Correction:

1 THE FOLLOWING
AREAS ARE
APPROVED

Partial Correction:

2 STAIR TOWER 1

EAST STAIRWELL

OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT
STAIRWELLS INSIDE FACE & BACKSIDE PRE-ROCK BETWEEN JOISTS: #1:

BASEMENT LEVEL: 1ST LAYER; 2ND LAYER

1ST FLOOR: 2ND LAYER

2ND FLOOR: 2ND LAYER

3RD FLOOR: 2ND LAYER

4TH FLOOR:

****BACKSIDE PRE-ROCK BETWEEN TRUSS-2ND LAYER DONE AT THE SAME TIME
AS WALL**

Partial Correction:

3 STAIR TOWER 2

OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT
STAIRWELLS INSIDE FACE & BACKSIDE PRE-ROCK BETWEEN JOISTS:

BASEMENT LEVEL: 2ND LAYER

1ST FLOOR: 2ND LAYER

2ND FLOOR: 2ND LAYER

3RD FLOOR: 2ND LAYER

4TH FLOOR:

****BACKSIDE PRE-ROCK BETWEEN TRUSS-2ND LAYER DONE AT THE SAME TIME AS WALL**

Partial Correction:

4 ELEVATOR 1

OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT ELEVATOR SHAFT:

BETWEEN TRUSS JOISTS:

BASEMENT LEVEL: BACKSIDE PRE-ROCK 2 LAYERS

1ST FLOOR: BACKSIDE PRE-ROCK 2 LAYERS

2ND FLOOR: BACKSIDE PRE-ROCK 2 LAYERS

3RD FLOOR: BACKSIDE PREROCK 2 LAYERS

4TH FLOOR:

Comments: