

# Inspection Summary

Permit #: PRRES20192617, Building Permit - Residential

Address: 2013 NE BLUESTONE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection:         | Inspector:    | Outcome: | Date:                  |
|---------------------|---------------|----------|------------------------|
| Driveway Inspection | Steve Robbins | Partial  | Friday, March 27, 2020 |

Informational

1 Driveway was formed with compacted rock. Ready to pour.

|                          |               |         |                        |
|--------------------------|---------------|---------|------------------------|
| DE - Sidewalk Inspection | Steve Robbins | Partial | Friday, March 27, 2020 |
|--------------------------|---------------|---------|------------------------|

Informational

1 Sidewalk is formed with compacted rock, and appears to meet all ADA requirements. Ready to pour.

Comments: