CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSITE20191519Address:701 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
DE - Storm - Pipe		Joe Starlin	Passed	Friday, October 18, 2019	
Informational:					
1	Misc	8-13-19 11:27am They hav to A-3.	e approximately 120 feet o	f storm installed working	
Informational:					
2	Misc	8-12-19 They are cutting into the existing box to run storm pipe from A-1 into it. They got 200 foot of storm pipe installed Friday. They are backfilling with watered down shell and will be getting compaction test from Terricon. I told them that the shell needs to be crushed down a little more than what they have at 200 feet from the box. 12:01pm They are getting ready to place A-2 box. 1:56pm A-2 box is placed and they are digging across the road. C-1 is placed and pipe ran. They have two sticks of pipe coming out of A-2 heading for A-3 box. The collars have been poured on A-1 A-2 and C-1.			
Informational:					
3	Misc	-	set box A-1 and are now set en installed. They are diggi		
Informational:					
4	Misc	working on installing new	is ran. They will be pouring v curb inlet along Ward. The 4. The curb inlet has been in	collars and inverts are	
Informational:					
5	Misc		nstalled 3 sticks of storm he ready to place E-2 box. 3:14	-	

		and are installing pipe to E-3		
Informati	onal:			
6	Misc	8-5-19 They have set E-1 box and are placing pipe up to it. They will be pouring collars at approximately 4:30pm.		
Informational:				
7	Misc	8-14-19 9:14am Box A-3 and B-1 are in and they are pouring collars right now.		
		They are installing 15" storm along Chipman as well.		
Informational:				
8	Misc	8-15-19 9:15am They are installing storm pipe along Chipman RD. They have		
		16 feet installed and are close to setting a box F-1. 2:20pm They have		
		installed approximately 25 additional feet and box F-1. They have poured		
		collars and backfilled with rock.		

Comments: