

Inspection Summary

Permit #: PRSUBD20200031, Development - Subdivision

Address: 6 NW ORCHARD ST, LEES SUMMIT, MO 64063 10 NW MAIN ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Grading/Excavation/Fill Inspection	Steve Robbins	Passed	Friday, April 03, 2020
DE - Sanitary - Material Verification	Steve Robbins	Passed	Friday, April 03, 2020
DE - Sanitary Sewer Construction Inspection	Steve Robbins	Passed	Friday, April 03, 2020
Informational			
1	The line has been constructed and all the testing has been completed and passed. The camera test has also passed.		
DEI - Sanitary Sewer - Camera Test	Steve Robbins	Passed	Friday, April 03, 2020
Informational			
1	The camera test has been completed and the sanitary lines have been accepted by the water department.		

Comments: