

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20173051
Address: 1980 SE BLUE PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Khanh Nguyen	Partial	Friday, April 03, 2020

Partial Correction:

1 ELEVATOR 1

ELEVATOR SHAFT:

1ST FL: 1" shaft liner ok; elev/shaft wall ok; outer layer ok except below

****Need to patch the wall above the restroom all the way to the steel beam.**

2ND FL: 1" shaft liner ok; elev/shaft wall ok; outer layer ok

3RD FL: 1" shaft liner ok; elev/shaft wall ok; outer layer ok except below

****close gap of outer layer at west/front intersection**

ELEVATOR MECHANICAL SHAFT:

2ND FL: 1-hr lid ok; 1" shaft liner ok; outer layer ok

3RD FL: 1" shaft liner ok; outer layer ok

MID-BUILDING MECHANICAL SHAFT:

2ND FL: 1-hr lid ok, outer layer ok

3RD FL: 1-hr lid ok, outer layer ok

Partial Correction:

2 STAIR TOWER 1

The following areas:

1st Floor-outer side OK; inner side ok

2nd-floor-outer side OK; inner side ok

**cover exposed steel w/ firerock

3rd floor-outer side OK; inner side ok

***"STAIR TOWER 1 IS THE STAIR ENCLOSURE NEAR THE SE END OF BUILDING

Partial Correction:

3 STAIR TOWER 2

The following areas:

1st Floor-outer side OK; inner side ok

2nd-floor-outer side OK; inner side ok

**cover exposed steel w/ firerock

3rd floor-outer side OK; inner side ok

***"STAIR TOWER 2 IS THE STAIR ENCLOSURE AT THE NORTH END OF BUILDING

Comments: