

Inspection Summary

Permit #: PRSITE20183647, Development - Site
PARAGON STAR

Address: 1401 NW VIEW HIGH DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Storm - Outlet Structure	Steve Robbins	Partial	Wednesday, April 08, 2020

Informational

- 1 The contractor has been working on forming up the final toe-wall/ end section on line 300 which has been installed. They were pumping the water out and getting ready to pour for tomorrow.

Comments: