## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20182604Address:837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:		
All Rough Commerc	Inspection - cial	John Borns	Partial	Friday, January 03, 2020		
Partial Co	rrection:					
1	Misc		OK TO COVER WHEN READY WOOD FRAMED WALLS/CEILINGS AND SYSTEMS TO BE ENCLOSED AT:			
			A.6 AT SECOND FLOOR AB EINFORCED WHERE NOTC	OVE FIREPLACE AFTER DOUBLE HED FOR PLUMBING;		
		CEILING AT GARAGE	#1 NORTH 6';			
		WING SEPARATION	FIREWALLS AT:			
		LEFT WING: 4TH FLO	OR; 3RD FLR; 2ND FLR; 1S	T FLR		
Partial Co	rrection:					
2	Misc	4TH FLOOR: LEFT WI 3RD FLOOR: LEFT WI 2ND FLOOR: LEFT W	VHEN READY AT CHASES E NG; CENTER; [RIGHT WIN NG; CENTER; [RIGHT WIN ING; CENTER; [RIGHT WIN NG; CENTER; [RIGHT WIN	G G IG		
Partial Co	rrection:					
3	Misc	OK TO FOAM AND IN 4TH FLOOR: LEFT WI	NSULATE ABOVE CEILING / NG;	AT:		
Partial Co	rrection:					
4	Misc	OK TO COVER WALL	S AND CEILINGS AT:			

		LEFT WING: 4TH FLOOR; ROUGH-IN; RC CHANNEL; RIGHT WING FIREWALL ABOVE CEILING @ ELEV #2 & UNITS N; 3RD FLOOR; ROUGH-IN; RC CHANNEL 2ND FLOOR; ROUGH-IN; RC CHANNEL	
		1ST FLOOR: ROUGH-IN @ UNITS ONLY INCLUDING 111, 119, 121; GARAGES, CORRIDOR, STORAGE RMS, JAN RM; RC CHANNEL @ UNITS ONLY; RC CHANNEL @ CEILINGS AT GARAGES, STORAGE, ELECT/MECH, JAN RMS; RC CHANNEL @ CEILINGS & WALLS AT CORRIDOR; OSB SHEATHING AT SHEAR WALL 6 AT SPRINKLER ROOM;	
		CENTER SECTION:	
		RIGHT WING:	
Partial Co	prrection:		
5	Misc	OK TO COVER THREE WALLS AT STAIRWELLS:	
		AT 1ST FLOOR: STAIRWELLS 1, 2, 3, 4	
		AT 2ND FLOOR: STAIRWELLS 1, 4, 2, 3	
		AT 3RD FLOOR: STAIRWELLS 1, 4, 2, 3	
		AT 4TH FLOOR: STAIRWELLS 2, 3, 4	
Partial Correction:			
6	Misc	OK TO COVER WHEN READY:	
		LIGHT-GAUGE STEEL FRAMED CEILING FUR-DOWNS AT: (1)228; (1)229;	
		SPACE ABOVE BOTTOM CHORD OF JOISTS AT: BA IN MOTHER-IN-LAW UNIT @	
		RIGHT WING; VESTIBULES AT (1)211 & (1)217;	

Comments: