CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063

(816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20183215

Address: 1420 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Footing Inspection -Mark Harding Partial Thursday, April 09,

Commercial 2020

Partial Correction:

PERIMETER FOOTING: 1 Misc

LINE 5/B-E;

LINE 5/E-L; LINE 2.3/A-B; LINE 4/A-B; LINE A/1.1 TO 4.1; A 4-5 1 LINE; LINE 1/A TO C; LINE 1/F to H; NEED CLARIFIFICATION ==>LINE G 4-2.3 - 3/31/20;K1

J-H;J1-2.2; J-K 2.2-3.2;

4/8/20 LINE L 3.2 TO 4.5 SW END

EXTERIOR GB PIER BASES: LINE 2.2/J, K, AND K.5; LINE 1/H.6 AND J; J/1.4; LINE

A/4.7 AND 5; LINE 1/E & D;

OK TO POUR WHEN READY ISOLATED COLUMN FOOTINGS AT LOCATIONS: B/2; B/3; B/4; C/2; C/4; D/2; D/3; D/4; E/2; E/3; E/4; F/2; F/3; F/4; G/2; G/3; G/4;

H/2; H/3; H/4; J/3; J/4; K/3; K/4;

3/13/20

***GUYS-PUT EXTERIOR GRADE BEAM ON THE FIRST SECTION: EXTERIOR GB PIER BASES ON THE 2ND SECTION, AND ALL INTERIOR COLUMN BASES ON THE **3RD SECTION**

Corr	ective	Action	Ren	uire	d٠
COLL	CCLIVC	ACCIOIL	1100	unc	u.

2 ELEVATOR 1 ELEVATOR BASE FOOTING, ELEVATOR WALLS BELOW GRADE

Comments: