

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20172529  
Address: 261 NW KESSLER DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Michael Harkins	Partial	Friday, April 10, 2020

Informational:

1	THIRD FLOOR	- screw pattern 3rd floor unit & corridor walls & ceilings OK -
Corrective Action Required:		
2	STAIR TOWER 1	- 3rd floor screw pattern walls & ceiling OK -
Corrective Action Required:		
3	STAIR TOWER 2	- 3rd floor screw pattern walls & ceiling OK -
Corrective Action Required:		
4	STAIR TOWER 3	- 3rd floor screw pattern walls & ceiling OK -
Corrective Action Required:		
5	STAIR TOWER 4	- 3rd floor screw pattern walls & ceiling OK -

**Comments:**