CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20193318Address:4400 SW ALABASTER CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Friday, April 17, 2020

Corrective Action Required:

00110001	e neuron negan car	
1	Misc	 Install steel column at beam in garage per plans
		 Hurricane strap missing at truss SW garage
		 Security blocking at exterior door in garage
		- Fireblock at DWV fur out in garage to 2nd floor
		 Attach joist hangers properly at LVL by stairs in living room
		- Fireblock at DWV between basement and 1st floor bath
		- Complete basement bath exhaust fan discharge line
		- Fire seal top plate electrical penetration in 1st floor bedroom
		- Fire seal top plate penetrations at low volt 2nd floor master bedroom

Comments: