CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192156 Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: | |
|---|-----------------------|----------------------------------|--|------------------------------|--|
| Underslab Electrical Inspection - Michael Harkins Commercial | | | Partial | Wednesday, April 22, 2020 | |
| Correc | tive Action Required: | | | | |
| 1 | THE FOLLOWING | Loading dock | | | |
| | AREAS ARE | A-C 1.9-5.2 elect; DLINE 4-6;7-8 | | | |
| | APPROVED | E LINE 7-8 | | | |
| | | E LINE 8-9 | | | |
| | | - Gondola E to F - | | | |
| | | - Data G to H - | | | |
| | | - B refer system 5.5 to 3 | 7.2 - | | |
| | | -E-8.5;6- 9 | | | |
| | | F-10- 9-e | | | |
| | | 4/17/20 F 7.5-10 @ SID | SIDE DOOR - | | |
| | | - 4/20/20 E 7 CANDY D | DISPLAY, 3/0 GROUND FOR COOLERS REAR WALL, | | |
| | | CONDUIT AT GONDOLO | DAS NE - | | |
| | | - 4/22/20 E-F 1 TO 6.5 I | LOOR BOXES - | | |

Comments: