

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20190654

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500  
NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>DE - Sanitary Sewer - Air Test</b>	Ronald Paynter	Passed	Thursday, April 23, 2020

Informational:

1	Misc	The following sanitary lines passed their air test: manhole existing 28-208 to 1-1, 1-1 to 1-2, 1-2 to 1-3, 1-3 to 1-4, and 1-4 to 1-5. RP 1-7-2020
---	------	---

Informational:

2	Misc	The following sanitary lines passed their air test. Manholes 1-5 to 1-6, 1-6 to 1-7, 1-7 to 3-1 and 3-1 to 3-2. RP 2-7-20
---	------	---

Informational:

3	Misc	The following sanitary lines passed their air test: 1-7 to 1-8, 1-8 to 1-9, 1-9 to 1-10, 1-10 to 1-11, 1-11 to 1-12, 1-12 to 1-13 and 1-10 to 4-1. RP 3-5-20
---	------	--

Informational:

4	Misc	The following sanitary lines passed their air test: 1-7 to 1-8, 1-8 to 1-9, 1-9 to 1-10, 1-10 to 1-11, 1-11 to 1-12, 1-12 to 1-13 and 1-10 to 4-1. RP 3-5-20
---	------	--

Corrective Action Required:

5	Misc	The following sanitary line failed the air test: 8-1 to 8-2. Jim Weers thinks he knows what could have caused the failed test. We will retest the line again in the future. RP 3-6-20
---	------	---

Informational:

6	Misc	The following sanitary lines passed their air test: 8-0 to 8-1, 8-2 to 8-3, 8-3 to 8-4, 8-4 to 8-5, 8-5 to 8-6 and 8-6 to 8-7. RP 3-6-20
---	------	--

Informational:

7	Misc	The following sanitary lines passed their air test: 11-5 to 11-4, 11-4 to 11-3,
---	------	---

11-3 to 11-2, 11-2 to 11-1 and 11-1 to existing MH 28-103. RP 4-14-20

Informational:

8 Misc

The following sanitary lines passed their air test: Existing manhole 28-100 to 10-1, 10-1 to 10-2, 10-2 to 10-3, 10-3 to 10-4, 10-4 to 10-5, 11-3 to 12-1, 12-1 to 12-2, 12-2 to 12-3, 12-3 to 12-4, 12-4 to 12-5 and 12-1 to 13-1. RP 4-16-20

Informational:

9 Misc

All sanitary lines have passed their air test. RP 4-20-20

**Comments:**