## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192156 Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Under: Comm	slab Electrical Inspectio ercial	n - Michael Harkins	Partial	Friday, April 24, 2020	
Correct	tive Action Required:				
1	THE FOLLOWING	Loading dock			
	AREAS ARE	A-C 1.9-5.2 elect; DLINE 4-6;7-8			
	APPROVED	E LINE 7-8			
		E LINE 8-9			
		- Gondola E to F -			
		- Data G to H -			
		- B refer system 5.5 to	7.2 -		
		-E-8.5;6- 9			
		F-10- 9-e			
		4/17/20 F 7.5-10 @ SIC	E DOOR -		
		- 4/20/20 E 7 CANDY D	DISPLAY, 3/0 GROUND FOR COOLERS REAR WALL,		
		CONDUIT AT GONDOLO	DLOAS NE -		
		- 4/22/20 E-F 1 TO 6.5	LOOR BOXES -		
		-BEER COOLERS TO H 4	.2 -		

Comments: