

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172529
Address: 261 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Michael Harkins	Failed	Friday, April 24, 2020

Informational:

1	STAIR TOWER 2	- 3rd floor screw pattern walls & ceiling OK - - 2ND FLOOR SCREW PATTERN WALLS & CEILING -
---	---------------	-----------------------------------------------------------------------------------------------

Informational:

2	STAIR TOWER 1	- 3rd floor screw pattern walls & ceiling OK - - 2ND FLOOR SCREW PATTERN WALLS & CEILING OK -
---	---------------	--------------------------------------------------------------------------------------------------

Informational:

3	THIRD FLOOR	- screw pattern 3rd floor unit & corridor walls & ceilings OK -
---	-------------	-----------------------------------------------------------------

Corrective Action Required:

4	FIRST FLOOR	-FOLLOWING AREAS REPLACE TYPE X WITH TYPE C UNIT 109 ENTRY CLOSET G5 CORRIDOR UNIT 109 TO G5 ELECTRICAL ROOM 10" SCREW PATTERNS SHALL BE 8"
---	-------------	------------------------------------------------------------------------------------------------------------------------------------------------------------

Comments: