

Inspection Summary

Permit #: PRSITE20191837, Development - Site

REECE NICHOLS

Address: 222 SW MAIN ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Fire Line - Flush	Steve Robbins	Passed	Tuesday, April 28, 2020

Informational

- 1 The contractor flushed the fire line after the tie in as we were flushing the main. The fire line and water main was flushed for approximately 25 minutes.

Comments: