CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192156 Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Underslab Electrical Inspection - Michael Harkins Commercial		Inspector:	Outcome:	Date:
		Partial	Wednesday, April 29, 2020	
Correc	tive Action Required:			
1	THE FOLLOWING	Loading dock		
	AREAS ARE	A-C 1.9-5.2 elect; DLINE 4-6;7-8		
	APPROVED	E LINE 7-8		
		E LINE 8-9		
		- Gondola E to F -		
		- Data G to H -		
		- B refer system 5.5 to	7.2 -	
		-E-8.5;6- 9		
		F-10- 9-e		
		4/17/20 F 7.5-10 @ SID	E DOOR -	
		- 4/20/20 E 7 CANDY D	ISPLAY, 3/0 GROUND FO	DR COOLERS REAR WALL,
		CONDUIT AT NE -		
		- 4/22/20 E-F 1 TO 6.5 I	LOOR BOXES -	
		-BEER COOLERS TO H 4	.2 -	
		G,H-4-6.5		
		- 4/29/20 TEA BAR & SI	EATING AREA UNDER W	INDOWS -

Comments: