

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20193076
Address: 4525 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Wednesday, April 29, 2020

Corrective Action Required:

- | | | |
|---|------|---|
| 1 | Misc | <ul style="list-style-type: none">• Fireblock above fireplace, complete fireplace b vent to exterior• Address Romex NM behind flue at fireplace• Missing ceiling joist hangers living room N• Terminate Ceiling NM romex , E bedroom, and dining room• Anchor bolt within 12" of plate break in basement by garage door• Tighten all anchor bolts at basement• Master bath address ceiling joist to rafter connection at ridge N wall and add collar ties according to plan• 800 lb hold down master bedroom• Fireblock at deadspace between bathroom showers in basement• Support rafters to ceiling joist at E wall by sliding doors |
|---|------|---|

Comments: