

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20200564
Address: 1920 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Pool Steel/Bonding - Residential	Khanh Nguyen	Partial	Monday, May 04, 2020

Partial Correction:

1	Misc	POOL BONDED: 4 SHELL REBAR BONDED AT 4 EQUALLY SPACED POINTS AROUND POOL; HANDRAIL, LADDER, JUMPER TO EQUIPMENT LOCATION
---	------	---

Comments: