## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20172525 Address: 249 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspec	ction:	Inspector:	Outcome:	Date:	
All Ro Comm	ugh Inspection - nercial	Michael Harkins	Failed	Monday, May 04, 2020	
Correc	tive Action Required:				
1	THIRD FLOOR	SOUTH EAST END			
		- 308 ROOF BOOTS AB	- 308 ROOF BOOTS ABOVE TUB, H 2.5s EXTERIOR WALL -		
		- 307 H 2.5s EXTERIOR	307 H 2.5s EXTERIOR WALL -		
		- 306 ROOF BOOTS -			
Correc	tive Action Required:				
2	SECOND FLOOR	- 206 FIRE COLLAR DEAD SPACE -			
Correc	tive Action Required:				
3	FIRST FLOOR	- 106 FIRE BLOCK DEAD SPACE, FIRE COLLAR -			
		- G8 ADD STUD UNDER	R TRIPLE LVL -		

## **Comments:**