

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20193076
Address: 4525 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Monday, May 04, 2020

Corrective Action Required:

- | | | |
|---|------|--|
| 1 | Misc | <ul style="list-style-type: none">• Fireblock above fireplace, no romex penetration through sheet metal• Address Romex NM at top, behind flue at fireplace• Terminate Ceiling NM romex , E bedroom, dining room, terminate NM romex at fireplace• Fireblock at deadspace between bathroom showers in basement |
|---|------|--|

Comments: