

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRCOM20190679  
Address: 222 SW MAIN ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Miscellaneous Inspection</b>	Mark Harding	Failed	Tuesday, May 12, 2020

Corrective Action Required:

1	Misc	pre-final notes> as walked through for above ceiling. vertical grab bars over 41" from rear wall. Break room sink and counter top over 34", check plans for compliance. ADA max for break room sink is 34". > mirror max height to reflective edge is 40" tile set in restrooms mirror will have to be offset.
---	------	---

**Comments:**