CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSITE20192517 Address: 2700 NE MCBAINE DR, Unit:IR, LEES SUMMIT, MO 640642700 NE MCBAINE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
DE - Fire Line Constru Inspection	ction John Jackson	Partial	Wednesday, May 13, 2020	
Informational:				
1 Misc	fire line and a 8" val chlorine. All ductile	Contractor (Kat Construction) installed an 8" sleeve & 8"X8" tee tie in for the fire line and a 8" valve. All fittings and pipes up to 8" valve were swab with chlorine. All ductile fittings were wrapped in plastic. Contractor poured backing block. Line was flushed placed back in service.		

Comments: