## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192495

Address: 2931 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Inspection Khanh Nguyen Partial Thursday, May 14,

2020

Corrective Action Required:

1 Misc -Med gas wall must be rated one hour with exposure on both sides

\*\*OK TO ROCK MED GAS RM WALLS ON BOTH SIDES. I WILL NEED A LADDER TO VERIFY. THE 2X4 STUD WALL OF THE MED RM MUST BE ROCKED ON BOTH

SIDES WITH 5/8" TYPE X GYP

## **Comments:**