

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20193476  
Address: 4413 SW NAUTILUS PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Robb Popp	Not Ready	Friday, May 15, 2020

Corrective Action Required:

1	Misc	-SIGNIFICANT WORK STILL BEING DONE AT INSPECTION- <ul style="list-style-type: none"><li>• Anchor all steel columns to floor in basement</li><li>• Seal low volt penetration through fire blocking at S basement by door</li><li>• Tighten all bottom plate anchor nuts in basement</li><li>• Gas line through joists at deck move down, 3" for penetration</li><li>• Ledger locks at deck install per manufacturer listing</li><li>• Column missing in basement by backdoor pier</li><li>• Duct through double header at window by sliding door in basement</li><li>• No electrical found below suspended slab in basement</li><li>• Fireblock at beam S wall basement by door</li><li>• Support joist at cutout below suspended slab stoop</li><li>• Firestop DWV at top plate basement N</li><li>• Protect pex at shower basement N</li><li>• Seal pex penetration at top plate bathroom N basement</li><li>• Firestop at basement bedroom N at dryer vent and DWV</li><li>• Support DWV in basement every 4'</li><li>• Fireblock at 2x6 above fireplace</li><li>• Complete all fire stopping throughout</li><li>• Install truss bracing per plans</li><li>• B vent flue within 1" combustible at truss bracing in attic</li><li>• Portal framing hold down in garage</li></ul>
---	------	---

- LVL corner to corner master bed, dining room, kitchen per plans
- Protect and install gas flex line at deck fireplace
- Remove green bonding screw from sub panel

**Comments:**