

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20193591  
Address: 117 NW MACKENZIE DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Michael Harkins	Failed	Thursday, May 21, 2020

Informational:

1 Misc Inspected garage portal framing only

Corrective Action Required:

2 Misc

- VENT ALL BATH EXHAUST TO EXTERIOR CONNECT WITH METALLIC TAPE -
- PROVIDE PFH PORTAL FRAME PER PLAN GARAGE DOOR tighten 5/8 ANCHOR BOLTS
- TIGHTEN ANCHOR BOLTS BASEMENT - at 3 window egress others covered by insulation
- PROVIDE TWO 3" SCH 40 COLUMNS UNDER BEAM AT STAIRWAY PER PLAN - plans says two

**Comments:**