

# Inspection Summary

Permit #: PRCOM20192670, Building Permit - Commercial  
STREETS OF WEST PRYOR LOT 10  
Address: 920 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Field Services	Joe Starlin	Failed	Thursday, May 21, 2020

Corrective Action Required

1. sod needs to be installed.
2. Landscaping needs to be finished.

We cannot issue a substantial completion or final acceptance until the development finishes installing the road and the signals. This is work that Emery Sapp is doing on the development side.

Comments: