## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20200716

Address: 910 NW BLUE PKWY, Unit:W, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection Khanh Nguyen Partial Friday, May 22, 2020

Partial Correction:

1 Misc IN-WALL OK TO COVER:

-THE REAR 6" DEMISING WALL; EAST 4" WALL

\*\*YOU CAN START ROCKING THE EXERCISE BIKE ROOM ONE-SIDE ONLY

**CORRECTIONS:** 

-PROTECT PLUMBING AT BOTTOM WALL TRACK WITH MIN. 2" OF PROTECTION

**BEYOND THE TRACK** 

-SECURE IN-WALL 2" OR SMALLER PLUMBING AT MID-WALL HEIGHT

-LAUNDRY STAND PIPE SHALL EXTEND MIN 18" AND NO MORE THAN 42"

ABOVE THE TRAP WEIR

-INSTALL BLOCKINGS FOR THE RESTROOM GRAB BARS

**Comments:**