

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	Michael Harkins	Partial	Wednesday, May 27, 2020

Corrective Action Required:

1	Misc	CONDUIT BETWEEN LIGHT POLES- FRONT EAST FACE: NE CORNER SOUTH 3 POLES; WEST FACE NW LIGHT POLES * - CONDUIT NORTH END & SOUTH END WOOD FRAME TO REAR & TO BUILDING FOUNDATION - - CONDUIT 2 TRENCHES FRONT OF STEEL BLDG TO STREET - WEST SIDE-- NORTH TO THE SOUTH CONDUIT 1,2,3;
---	------	--

Informational:

2	Misc	140' Conduit for light poles rear of apt building near retaining wall from transformer to fire hydrant
---	------	---

Comments: