

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20200564  
Address: 1920 NE CATALINA AVE, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Pool Steel/Bonding - Residential</b>	Khanh Nguyen	Failed	Thursday, June 04, 2020

Partial Correction:

1	Misc	POOL BONDED: 4 SHELL REBAR BONDED AT 4 EQUALLY SPACED POINTS AROUND POOL; HANDRAIL, LADDER, JUMPER TO EQUIPMENT LOCATION
		**THE BONDING CLAMP AT THE BACK SIDE OF THE POOL IS BROKEN
		**RESTORE THE EROSION CONTROL ALONG THE REAR OF THE HOUSE

Comments: