

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Underground Electrical Inspection - Commercial</b>	Robb Popp	Partial	Monday, June 08, 2020

Corrective Action Required:

1	Misc	CONDUIT BETWEEN LIGHT POLES-  FRONT EAST FACE: NE CORNER SOUTH 3 POLES; WEST FACE NW LIGHT POLES * - CONDUIT NORTH END & SOUTH END WOOD FRAME TO REAR & TO BUILDING FOUNDATION - - CONDUIT 2 TRENCHES FRONT OF STEEL BLDG TO STREET - WEST SIDE-- NORTH TO THE SOUTH CONDUIT 1,2,3; -CONDUIT AND GROUND RODS FOR LIGHT POLE BASES (1) NORTH, (5) EAST, (1) SOUTH, (1) SOUTHWEST -CONDUIT FROM SOUTHWEST LIGHT POLE UNDER STREET TO SOUTH LIGHT POLES WITH CONDUIT NORTH BACK TO BUILDING AND CONNECTING WEST LIGHT POLE
---	------	---

Informational:

2	Misc	140' Conduit for light poles rear of apt building near retaining wall from transformer to fire hydrant
---	------	--

Comments:

