## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Piers/Caissons Inspection - Commercial		Inspector: Michael Harkins	Outcome: Partial	Date: Monday, June 15, 2020	
					Inform
1	Miscellaneous	LIGHT POLE BASE:			
	Correction	-1 24" SOUTH SIDE			
		-1 24" NORTH SIDE			
		-1 24" SOUTHEAST COP	-1 24" SOUTHEAST CORNER		
		-4 6'X6' PADS EAST SID	4 6'X6' PADS EAST SIDE		
		-1 24" SOUTHWEST CO	RNER		
		-6/15/20- RETAINING V	6/15/20- RETAINING WALL REAR OF APTS		
		(4) LIGHT POLE BASE REBAR CAGES, DRIVEN GROUND ROUND			
Correct	ive Action Required:				

2 Miscellaneous Correction

Comments: