

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Mark Harding	Failed	Monday, July 13, 2020

Informational:

1	Misc	- METAL STUD FRAMING AT LOBBY ENTRANCE - - METAL STUD WALL NORTH SIDE LOBBY -
---	------	--

Corrective Action Required:

2	FOURTH FLOOR	AREA "E"- UNITS-(2 far south not ready) Section E phase 1 439 Rock and caulk shower wall. 440- Truss bearing at corridor wall nail Joist Hangers. 461- elect land ground 460-washer puddy pads or 5 side box. 441- elect land ground 442-elect land ground, Provide 1 1/2 " bearing truss East bath wall- 443-OK 459-laundry & dryer box-5side Need Clarification on Egress window opening. Install 5 sided box for dryer boxes.
---	--------------	--

**Comments:**

