

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172533
Address: 265 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Michael Harkins	Partial	Friday, July 31, 2020

Corrective Action Required:

1	LOWER LEVEL	- NORTH END - - REAR ENTRY H2.5'S TRUSS ABOVE DOOR - - 102 BOCA PLATE FIRE LINE MASTER BATH -
---	-------------	---

Corrective Action Required:

2	FIRST FLOOR	- NORTH END - - G-1 FIRE BLOCK BOTTOM PLATE REAR WALL - - G-6 FIRE BLOCK BOTTOM PLATE REAR WALL - - SOUTH END - - 108 FIRE CAULK TOP PLATE MASTER BATH -
---	-------------	--

Corrective Action Required:

3	SECOND FLOOR	- NORTH END - - 304 PROVIDE BATH EXHAUST - - SOUTH END - - G-7 FIRE CAULK LOW VOLT PENETRATIONS - - 206 NAIL JOIST HANGER ON DECK - - 208 STRAP DWV MID POINT MECHANICAL ROOM, SECURE SERVICE ENTRY CABLE LAUNDRY ROOM -
---	--------------	--

Comments: