

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20200943
Address: 1606 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Wednesday, August 05, 2020

Corrective Action Required:

- | | | |
|---|------|---|
| 1 | Misc | <ul style="list-style-type: none">- Secure ward flex at fireplace- Solid block above lvl beam through living room per plans- Security blocking at basement walkout- Joist hangers at header in basement by windows- Furred down, ceiling 2x4 laid flat over 3' needs to be supported to the floor joists above to support the ceiling load in basement- Fireblock vertical to horizontal at furred downs in basement |
|---|------|---|

Comments: