# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

All Rough Inspection - Robb Popp Partial Thursday, August 06,

Commercial 2020

Corrective Action Required:

1 FOURTH FLOOR AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460- 426-

Corridor 419 to room 439 ok Corridor 422 to stairs ok

Corrective Action Required:

2 THIRD FLOOR Section "E"

345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing

ceiling

Corridor 319 to room 364 ok Corridor 322 to stairs ok

Corrective Action Required:

3 SECOND FLOOR Section "E" Ok-241,242,243,244,245,261,262. 226.

Corridor 219 to room 240 ok Corridor 222 to stairs ok

-264- shower valve box corridor wall incomplete

Corrective Action Required:

4 FIRST FLOOR -CORRECT FIRESTOP AT CORRIDORS 119 and 122

134

-PROVIDE VERTICAL/ HORIZONTAL FIRESTOP AT DEMISING WALL

### 133

- -PROVIDE PROTECTION PLATE FOR PEX AT DEMISING WALL
- -MOVE CLEANOUT AT SHOWER TO ACCESSIBLE LOCATION
- -CORRECT SCREW PATTERN AT ROCK BEHIND SHOWER
- -PROVIDE NAIL GAURD FOR DWV IN SHOWER

# 127

-CORRECT FIRE RATING AT SHOWER VALVE IN DEMISING WALL

### 125

-SEAL PENETRATION IN BOTTOM PLATE AT BATH/ CLARIFY PROPER FIRE ASSEMBLY

# **Comments:**