

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172533
Address: 265 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Michael Harkins	Failed	Thursday, August 13, 2020

Corrective Action Required:

1	LOWER LEVEL	- NORTH END - - 102 BOCA PLATE FIRE LINE CORNER MASTER BATH (NOT DONE) - - 108 FIRE CAULK TOP PLATE MASTER BATH & CLOSET (NOT DONE)-
---	-------------	---

Corrective Action Required:

2	FIRST FLOOR	- NORTH END - OK - SOUTH END - - G-7 FIRE CAULK LOW VOLT PENETRATIONS TOP PLATE (NOT DONE) -
---	-------------	--

Corrective Action Required:

3	SECOND FLOOR	- NORTH END - OK - SOUTH END - OK
---	--------------	--

Comments: