

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20200564
Address: 1920 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Pool Final - Residential	Khanh Nguyen	Failed	Friday, August 14, 2020

Corrective Action Required:

1	Misc	-Adjust the east gate to fully self-close&latch -Paint gas piping to protect against corrosion
---	------	---

Comments: