

# Inspection Summary

Permit #: PRSITE20171570, Development - Site  
CONTROL SERVICES

Address: 3621 NE AKIN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Storm - Swales	Jeremy Young	Passed	Thursday, August 20, 2020
DE - Sanitary Sewer Construction Inspection	Steve Robbins	Passed	Thursday, August 20, 2020

Informational

- 1 John Jackson notified me that the contractor has installed the new top cone on the sanitary MH that is located in front of the building. This needed to be done because they put too many riser rings on the old MH.

Comments: