

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20201531
Address: 4399 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underslab Plumbing Inspection - Residential	Patrick Schonfeldt	Failed	Tuesday, August 25, 2020

Corrective Action Required:

1	Misc	- INTERIOR DRAIN TILE NEEDS TO REACH OPPOSITE END OF FOUNDATION FROM SUMP PIT WHEN LAYING INTERIOR DRAIN TILE DIAGONALLY
---	------	---

Comments: