



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20202373, Public Works Right of Way Permit  
Address: 4425 SW NAUTILUS PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Friday, August 28, 2020

Corrective Action Required  
1      Misc      Note: the last inspection on 8/28 was for another location.

Site visit: locate flags present, no workers.

Corrective Action Required  
2      Misc      Note: the last site visit on 8/28 was for another location.

Site visit: locate flags present, no workers present.

**Comments:**