

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20202373, Public Works Right of Way Permit Address: 4425 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Tuesday, September 01, 2020

Corrective Action Required

1 Misc Site visit: haven't seen any workers present, locate flags are

present.

**Comments:**