



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20202907, Public Works Right of Way Permit

Address: 2906 SW ARBORIDGE DR, LEES SUMMIT, MO 640823020 SW ARBORIDGE DR, LEES SUMMIT, MO 640823009 SW ARBOR TREE DR, LEES SUMMIT, MO 640821500 SW SUGAR TREE DR, LEES SUMMIT, MO 640821528 SW SUGAR TREE DR, LEES SUMMIT, MO 640821515 SW ARBOR FALLS DR, LEES SUMMIT, MO 640822919 SW ARBORWOOD DR, LEES SUMMIT, MO 640821516 SW ARBOR VALLEY DR, LEES SUMMIT, MO 640821537 SW ARBOR CREEK DR, LEES SUMMIT, MO 640821521 SW ARBOR CREEK DR, LEES SUMMIT, MO 640822911 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Friday, September 18, 2020

Corrective Action Required

1	Misc	Site visit: I spoke with some of the workers onsite and went over our specifications. I informed them bore depths need to be 36" below streets and 18" in green space. I also advised them drops or vaults need to be 2ft back of curb. I will continue to monitor the work. I also spoke with Eli the foreman onsite and went over the specifications. Eli stated they would be working for another two weeks on the project.
---	------	--

Comments: