



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20202907, Public Works Right of Way Permit

Address: 2906 SW ARBORIDGE DR, LEES SUMMIT, MO 640823020 SW ARBORIDGE DR, LEES SUMMIT, MO 640823009 SW ARBOR TREE DR, LEES SUMMIT, MO 640821500 SW SUGAR TREE DR, LEES SUMMIT, MO 640821528 SW SUGAR TREE DR, LEES SUMMIT, MO 640821515 SW ARBOR FALLS DR, LEES SUMMIT, MO 640822919 SW ARBORWOOD DR, LEES SUMMIT, MO 640821516 SW ARBOR VALLEY DR, LEES SUMMIT, MO 640821537 SW ARBOR CREEK DR, LEES SUMMIT, MO 640821521 SW ARBOR CREEK DR, LEES SUMMIT, MO 640822911 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Thursday, September 24, 2020

Corrective Action Required

1	Misc	Site visit: no activity, there area several vaults staged to be installed. The vaults that have been installed on lots that are not occupied are flush and the areas around the vaults that were disturbed appeared to have been graded properly. The vaults that have been installed in yards with sod, appear to have been installed without issue. Will continue to monitor the progress.
---	------	--

Site Visit Inspection	Matt Munger	Partial	Thursday, September 24, 2020
------------------------------	-------------	---------	------------------------------

Corrective Action Required

1	Misc	Site visit: As I was leaving the site I noticed a pit that had a vault placed in it but was not fenced off. One of the workers had pulled in as I was leaving. I stopped and informed him that pits need to be fenced off if no one is around.
---	------	--

Comments: