

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Michael Harkins	Partial	Thursday, September 24, 2020

Corrective Action Required:

1	FOURTH FLOOR	AREA"E"- UNITS- 435,436,437,438,439,440,461,441,442,459-443-459-461-462-463-464-465-460- 426;444,447,448,449,450,451,457,424A, 425A Corridor 419 to room 439 ok -CORRIDOR 419,422,426, 427, 429, CEILINGS & WALLS -
---	--------------	--

Corrective Action Required:

2	THIRD FLOOR	AREA "D" CORRIDOR 412, Section "E" 345-344-343- 342-361-362-363-341-364-340-322-326-327, 329, -corridor framing ceiling -321A, 324A, 325A, 337, 338, 339, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360,365, 366, 367 Corridor 319 to room 364 ok Corridor 322, 326, 327, 329,
---	-------------	--

Corrective Action Required:

3	SECOND FLOOR	SECTION "D" CORRIDOR FRAMING CEILING 312, Section "E" Ok- 224A,237,238,239,240,241,242,243,244,245, 246, 261,262.
---	--------------	---

225A, 226, 264,265,266,267 -
-,247,249,250,251,252, 253,254,256,257,258,259,260,

-248- SEAL DEAD SPACE AT FUTURE SHAFT

Corridor 219 to room 240 ok
Corridor 222 to stairs ok
- CORRIDOR 222 FROM STAIRS TO END OF CORRIDOR 226 -
SECTION "E"
- CORRIDOR 229 ALL ROUGH -

SECTION "D"
CORRIDOR CEILING FRAMING 212,

Corrective Action Required:
4 FIRST FLOOR

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY -
- NORTH RETAIL ALL ROUGH ---
- LOWER LOBBY NORTH & SOUTH ENDS 2HR DEMISING WALL -

Section "E" OK-121,122,123,124,125, 126, 127, 128, 129, 130, 131, 132, 133,
134, 135, 136, 137, 138,

Corridor 119 to room 125 ok
Corridor 122,129 ok
CORRIDOR CEILING 112, 129,
-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH
ENDS-

-ROOM 132-
-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Informational:
5 STAIR TOWER 3

STAIR TOWER 123 "C" NORTH AREAS INSPECTED:
- STAIR TOWER "C" -
- ALL ROUGH APPROVED -

Corrective Action Required:
6 STAIR TOWER 2

STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED:

Corrective Action Required:
7 STAIR TOWER 1

STAIR TOWER 107 "A" SOUTH AREAS INSPECTED:

Corrective Action Required:

Comments: