

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172525
Address: 249 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Morris	Failed	Friday, September 25, 2020

Corrective Action Required:

1 Misc

- Safety glazing required in window at stairway east exterior wall southside units
- Guard rail required rear of building stoop north and south side
- Tamper resistant Schrader valves at all AC Condensing units
- Broken window in bedroom of unit 104

Comments: