



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20202907, Public Works Right of Way Permit

Address: 2906 SW ARBORIDGE DR, LEES SUMMIT, MO 640823020 SW ARBORIDGE DR, LEES SUMMIT, MO 640823009 SW ARBOR TREE DR, LEES SUMMIT, MO 640821500 SW SUGAR TREE DR, LEES SUMMIT, MO 640821528 SW SUGAR TREE DR, LEES SUMMIT, MO 640821515 SW ARBOR FALLS DR, LEES SUMMIT, MO 640822919 SW ARBORWOOD DR, LEES SUMMIT, MO 640821516 SW ARBOR VALLEY DR, LEES SUMMIT, MO 640821537 SW ARBOR CREEK DR, LEES SUMMIT, MO 640821521 SW ARBOR CREEK DR, LEES SUMMIT, MO 640822911 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                    |
|------------------------------|-------------|----------|--------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Partial  | Friday, October 02, 2020 |

**Corrective Action Required**

|   |      |                                                                                                                        |
|---|------|------------------------------------------------------------------------------------------------------------------------|
| 1 | Misc | Site visit: It appears the majority of the work has been completed. The bore rig is still on site. No workers present. |
|---|------|------------------------------------------------------------------------------------------------------------------------|

**Comments:**