Inspection Summary			
Permit #: PRRES2020156	7, Building Permit - Residen	tial	
Address: 4030 SW BENZI	GER DR, LEES SUMMIT, MO	64082	
•	cted and the inspection res s have been completed. Do		•
Inspection Item: Inspection:	Inspector:	Outcome:	Date:
Plot Plan Inspection	Steve Robbins	Failed	Wednesday, October 14, 2020
	manhole 60-189 in the fron e dirt/debris off of it so it c the manhole.		
Comments:			