

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20201507
Address: 1840 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	John Morris	Failed	Tuesday, October 27, 2020

Corrective Action Required:

- | | | |
|---|------|---|
| 1 | Misc | <ul style="list-style-type: none">- Pex within 6" of recessed can light in kitchen, relocate or shield- Secure DWV 2" or less at mid point- Seal all penetrations through air returns and plenums- Complete gas line installation at fireplace- Stud shoes at DWV - 2nd floor bath- Protection plates at DWV top plate - 2nd floor bath- secure master bath DWV bottom plate protection plate |
|---|------|---|

Comments: